REPORT

GENERAL INFORMATION

Report Name
Kia Ceed

Read out date
2026-02-03 12:12:22

Date of editing
2026-02-03 16:03:58

Serial number
36037 Professional

Unit of measure
µm

VEHICLE DATA

Type	**HATCHBACK 5D**
Make	**Kia**
Model	**Ceed**
VIN	**U5YH2511AKL079956**
First registration	**1.2.2020.**
Fuel Type	**Gas**
Engine capacity [ccm]	**998**
Power [kW]	**88**
Year of production	**2019**

COMMENT

-

MEASUREMENTS

"- " means measurement skip, "∞ " means measurement out of range

PAS: General interpretation, Body



LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Left front fender/ bumper	Fe	76	102	92	76	98	90	102	-	-	-
Left front door	Fe + Zn	82	106	98	100	105	82	102	106	103	88
Left rear door	Fe	89	127	110	124	116	89	101	103	127	-
Left pillar	Fe	85	106	97	95	85	106	100	97	-	-
Left rear fender/ bumper	Fe	101	120	111	120	101	-	-	-	-	-



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Right front fender/ bumper	Fe	83	104	94	89	98	104	83	-	-	-
Right front door	Fe	77	109	99	77	106	109	106	86	106	103
Right rear door	Fe	141	255	198	196	242	255	141	183	173	-
Right pillar	Fe	89	151	114	151	139	89	89	100	-	-
Right rear fender/ bumper	Fe + Zn	148	353	251	148	353	-	-	-	-	-



TOP											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Hood/bonnet	Fe + Zn	76	128	104	128	79	128	76	109	-	-
Roof	Fe	93	118	105	93	103	110	118	99	-	-



BACK											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Trunk/boot	Fe	107	131	117	107	123	131	112	111	-	-

Legend
Disabled
Paint layer is too thin
Paint layer is original
Second layer of paint
A thin layer of putty
A thick layer of putty

MEASUREMENTS

"- " means measurement skip, "∞ " means measurement out of range

PAS: General interpretation, Int. body parts



LEFT SIDE											
	Coating	Minimum	Maximum	Medium	1. 8.	2. 9.	3. 10.	4. 11.	5. 12.	6. 13.	7. 14.
Left side	Fe	41	74	56	41 74	52 -	51 -	59 -	57 -	58 -	55 -



RIGHT SIDE											
	Coating	Minimum	Maximum	Medium	1. 8.	2. 9.	3. 10.	4. 11.	5. 12.	6. 13.	7. 14.
Right side	Fe	48	84	59	66 48	60 -	84 -	55 -	55 -	52 -	52 -



ENGINE COMPARTMENT											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Engine compartment	-	44	53	48	-	44	50	-	-	53	45



TRUNK/BOOT											
	Coating	Minimum	Maximum	Medium	1.	2.	3.	4.	5.	6.	7.
Trunk/Boot	Fe	28	39	35	35	37	39	28	35	36	-

CHARTS

EXTERNAL MEASUREMENTS



INTERNAL MEASUREMENTS



TIRES/TYRES

TIRES/TYRES					
	Manufacturer	Season	Size	Measurements	Measurements
Left front	Bridgestone	Winter	225/45/17	5mm	5mm
Right front	Bridgestone	Winter	225/45/17	5mm	5mm
Left rear	Bridgestone	Winter	225/45/17	6mm	6mm
Right rear	Bridgestone	Winter	225/45/17	6mm	6mm

SYMMETRIC MEASUREMENTS

EXTERNAL MEASUREMENTS														
Left front fender/ bumper	1. 76	2. 98	3. 90	4. 102	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -
Right front fender/ bumper	4. 83	3. 104	2. 98	1. 89	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -
Difference	**7**	**6**	**8**	**13**										
Left front door	1. 100	2. 105	3. 82	4. 102	5. 106	6. 103	7. 88	- -	- -	- -	- -	- -	- -	- -
Right front door	7. 103	6. 106	5. 86	4. 106	3. 109	2. 106	1. 77	- -	- -	- -	- -	- -	- -	- -
Difference	**3**	**1**	**4**	**4**	**3**	**3**	**11**							
Left rear door	1. 124	2. 116	3. 89	4. 101	5. 103	6. 127	- -	- -	- -	- -	- -	- -	- -	- -
Right rear door	6. 173	5. 183	4. 141	3. 255	2. 242	1. 196	- -	- -	- -	- -	- -	- -	- -	- -
Difference	**49**	**67**	**52**	**154**	**139**	**69**								
Left pillar	1. 95	2. 85	3. 106	4. 100	5. 97	- -	- -	- -	- -	- -	- -	- -	- -	- -
Right pillar	5. 100	4. 89	3. 89	2. 139	1. 151	- -	- -	- -	- -	- -	- -	- -	- -	- -
Difference	**5**	**4**	**17**	**39**	**54**									
Left rear fender/bumper	1. 120	2. 101	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -
Right rear fender/ bumper	2. 353	1. 148	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -	- -
Difference	**233**	**47**												
INTERNAL MEASUREMENTS														
Left side	1. 41	2. 52	3. 51	4. 59	5. 57	6. 58	7. 55	8. 74	- -	- -	- -	- -	- -	- -
Right side	8. 48	7. 52	6. 52	5. 55	4. 55	3. 84	2. 60	1. 66	- -	- -	- -	- -	- -	- -
Difference	**7**	**0**	**1**	**4**	**2**	**26**	**5**	**8**						

LAQO
by Croatia osiguranje

Oznaka izvida: LAQO17442349
Datum štete: 18.10.2021
Datum izvida: 31.01.2022
Tip zahtjeva:

MAXX AUTO d.o.o.
Gornjostupnička 18j,
Gornji Stupnik
servisty@kiacentar.hr
01/6589-082

Zapisnik o izvidu štete
br. 90-AK-1811/2022

Osnovni podaci o vozilu:

Marka, tip, model: KIA CEED/PROCEED (CD) OSNOVNI MODEL	Snaga motora: kW
Broj šasije (VIN): U5YH2511AKL079956	Stanje km ili RS: 18656
Godina proizvodnje: 2020	Boja:

Popis dijelova za popravak i zamjenu s procjenom potrebnih radova:

DIJELOVI ZA ZAMJENU:

Naziv dijela	Kataloški broj
ZAŠT FOLIJA VRA ST D	87549J7001
ZAŠT OD KAMENJA ST D	84221J7001

DIJELOVI ZA POPRAVAK ILI KONTROLU:

VRATA ST D POPRAVAK

BOČNA STRANICA ST D POPRAVAK

DIJELOVI ZA LAKIRANJE:

VRATA ST D

BOČNA STRANICA ST D

Vrsta laka: 2-SLOJNI-METALIK

RADOVI:

Radno vrijeme za popravak lim, meh, tap, plast, elek i ostali radovi osim lak:	6.10 sati	Radno vrijeme za lakiranje:	6.60 sati
Lakirerski potrošni materijal:	735.96 kn		

Upozorenje:

Ako se tijekom popravka vozila utvrde dodatna oštećenja, koja su u vezi s prijavljenim odštetnim zahtjevom, izvođač radova uz znanje vlasnika vozila, a prije započetog nastavka popravka, dužan je zatražiti naknadni izvid štete, jer u protivnom osiguratelj neće nadoknaditi neutvrđeni dio štete.

Ovaj izvid štete/kalkulacija popravka nije radni nalog za popravak vozila i ne predstavlja odluku o osnovanosti zahtjeva.

Napomena:

Komentar:

MAXX AUTO d.o.o.

Gornjostupnička 18J 10255 Gornji Stupnik Hrvatska

KUPAC: 0002463
UNICREDIT LEASING CROATIA D.O.O.
SAMOBORSKA CESTA 145
10000 ZAGREB
OIB: 18736141210

MAXX AUTO d.o.o.
Zagreb - Gornji Stupnik
Gornjostupnička 18j

01/6588-460	Telefon
01/6589-188	Telefax
prodajast@kmag.net	E-mail
24.08.2023	Datum
24.08.2023	Datum računa
24.09.2023	Datum dospjeća
24.08.2023	Datum otpreme
Gornji Stupnik	Mjesto izdavanja računa
Gornji Stupnik	Mjesto otpreme

MAXX AUTO d.o.o. PJ STUPNIK
Gornjostupnička 18J
10255 Gornji Stupnik
Hrvatska
Telefon: 01/6588-460
Telefax: 01/6589-188

OIB: 21927122933

Raiffeisenbank Austria d.d.
Rač.br.: HR9624840081106758824
Privredna banka Zagreb d.d.
Rač.br.: HR2623400091110798947
OTP banka d.d.
Rač.br.: HR8124070001100534211
Zagrebačka banka - Unicredit group
Rač.br.: HR3223600001102595690
Erste&Steiermärkische Bank d.d.
Rač.br.: HR7524020061100848671

Mj.troš.: 423040 LIMARSKA RADIONICA STUPNIK

Broj računa: 3068-1-91

I18-042-904/23-s
Poziv na broj: 8166969

P O D A C I

Popravak motornog vozila
Tip vozila kia ceed 1.0 t-gdi
Reg. ozn. ZG 1197 HP
Broj radnog naloga: 2102/23
Voditelj naloga: 191 BOŽIDAR BABIĆ
Broj šasije: U5YH2511AKL079956
KM stanje: 31880

Rb.	Opis	Kat. br.	JM	Kol.	Cijena (EUR)	VP Iznos (EUR)	Rabat (%)	Rabat (EUR)	Iznos (EUR)
1	NALEPNICA	*84221J7001	KOM	1	26,82	26,82	7,00	1,88	24,94
2	NALJEPNICA	*87549J7001	KOM	1	16,67	16,67	7,00	1,17	15,50
Materijal ukupno						43,49		3,04	40,45
3	Limarski radovi		SAT	6,1	42,00	256,20	0,00	0,00	256,20
4	Lakirerski radovi		SAT	6,6	42,00	277,20	0,00	0,00	277,20
5	Potrošni lakirerski materijal		KOM	1	97,74	97,74	0,00	0,00	97,74
Usluge ukupno						631,14		0,00	631,14

* Originalni rezervni dio

Ukupno	674,63
Rabat	3,04
Ukupan iznos bez PDV-a:	**671,59**
PDV 25 % :	**167,90**
Ukupan iznos sa PDV-om:	**839,48**

Ukupno kn (tečaj:7,53450): **6.325,08**

Slovima: osamstotinatrideseteevet 48/100 EUR

Način plaćanja: 003 TRANSAKCIJSKI RAČUN
Popravak po izvidu štete Laqo 90-AK-1811/2022

Račun izdao/la:

Odgovorna osoba:

M.P. auto MAXX

MAXX AUTO d.o.o.
Zagreb - Gornji Stupnik
Gornjostupnička 18J 5

Račun primio/la:

MAXX AUTO d.o.o. Gornjostupnička 18J 10255 Gornji Stupnik, Upisano u sudski registar Trgovačkog suda u Zagrebu pod brojem Tt-13/27469-2, MBS: 080884158, OIB:21927122933, Temeljni kapital 2.654,46 EUR (20.000,00 HRK) uplaćen u cijelosti, Član uprave: Domen Habič